



TEST REPORT

Report No.: E6930.01-201-44

Rendered to:

INTIGRAL Walton Hills, Ohio

PRODUCT TYPE: In-Swing Door with Interior Lift and Tilt Blind **SERIES/MODEL**: Innovia using 8070 CL Tempered

SPECIFICATIONS: WDMA 7-14 – Cycle Slam Test AAMA 920-11- Specification for Operating Cycle Performance of Side-Hinged Exterior Door Systems

Test Completion Date: 04/29/15

Reference must be made to Report No. E6930.01-201-44, dated 04/29/15 for complete test specimen description and detailed test results.





Test Report No.: E6930.01-201-44

Report Date: 04/29/15 Page 1 of 4

1.0 Report Issued To: Intigral

7850 Northfield Road Walton Hills, Ohio 44146

2.0 Test Laboratory: Architectural Testing, Inc.,

an Intertek Company ("Intertek-ATI")

849 Western Avenue North St. Paul, Minnesota 55117

651-636-3835

3.0 Project Summary:

3.1 Product Type: In-Swing Door with Interior Lift and Tilt Blind

3.2 Series/Model: Innovia using 8070 CL Tempered

3.3 Compliance Statement: Results obtained are tested values and were secured by using the designated test method.

3.4 Test Dates: 04/13/2015 - 04/29/2015

3.5 Test Record Retention End Date: All test records for this report will be retained until April 29, 2019.

3.6 Test Location: Intertek-ATI test facility in St. Paul, Minnesota.

3.7 Test Sample Source: The test specimen was provided by the client.

3.8 List of Official Observers:

<u>Name</u> <u>Company</u>

Tony Gavin Intertek-ATI Steve Kenemer Intertek-ATI





Test Report No.: E6930.01-201-44 Report Date: 04/29/15

Page 2 of 4

4.0 Test Specifications:

WDMA 7-14 – Cycle Slam Test

AAMA 920-11 – Specification for Operating Cycle Performance of Side-Hinged Exterior Door Systems

5.0 Test Specimen Description:

5.1 Product Sizes:

Overall Area:	Width		Height	
2.1 m ² (22.4 ft ²)	millimeters	inches	millimeters	inches
Overall size	956	37-5/8	2178	85-3/4
Leaf size	908	35-3/4	2115	83-1/4







Test Report No.: E6930.01-201-44

Report Date: 04/29/15 Page 3 of 4

5.0 Test Specimen Description: (Continued)

5.2 Glazing:

Glass Type	Spacer Type	Interior Lite	Exterior Lite	Glazing Method
1" IG	Intercept	Clear	8070	Wet

Logation	Quantity	Daylight Opening		Class Pita
Location	Quantity	millimeters	inches	Glass Bite
Panel	1	537 x 889	21-1/8 x 35	1/2

6.0 Test Results: The temperature during testing was 21°C (70°F). The results are tabulated as follows:

Title of Test	Results	Allowed	Note
Cycle Slam test,			
per WDMA 7-14			
250,000 cycles	Pass	Meets as stated	1
Operation/Cycling			
Performance,			
per AAMA 920-11	Pass		
250,000 cycles	Meets Class CW	Meets as stated	1

Note 1: Blind operation verified after every 25,000 cycles.





Test Report No.: E6930.01-201-44 Report Date: 04/29/15

Page 4 of 4

The service life of this report will expire on the stated Test Record Retention End Date, at which time such materials as drawings, data sheets, samples of test specimens, copies of this report, and any other pertinent project documentation, shall be discarded without notice.

If test specimen contains glazing, no conclusions of any kind regarding the adequacy or inadequacy of the glass in any glazed test specimen can be made. This report does not constitute certification of this product nor an opinion or endorsement by this laboratory. It is the exclusive property of the client so named herein and relates only to the specimen tested. This report may not be reproduced, except in full, without the written approval of Intertek-ATI.

For INTERTEK-ATI:	
Tony D. Gavin Technician	Daniel A. Johnson Director – Regional Operations
TDG/jb	
No attachments included.	

This report produced from controlled document template ATI 00499, issued 04/25/11.